



Project Observation Report

Observer Name: [REDACTED]
Phone: [REDACTED]
Email: [REDACTED]
Date of Report 2022-01-05

Project:	DEMOLITION OF FORMER SIXTH GRADE CENTER
Project Number:	5-2118-40
On Site Time:	12:00 pm – 1:00 pm
Date of Observation	2022-01-05
Weather:	15° Sunny
Winds:	N @ 10 mph
<u>Personnel on Site</u>	
Lucas Vanisko	Healy Bender Patton & Been Architects

Observations

1. Superstructure demolition at Warrior Dome is complete and lower-level demolition is in progress at approximately 5% complete. See photos (A), (B), and (C).
2. Demolition work on the Former Sixth Grade Center has not started.
3. Soils samples testing related to the underground storage tank that was removed north of the Former Sixth Grade Center is in progress for analysis of potential contaminants. Per Jensen Environmental, soils testing report will be sent the week of January 10th, 2022.





Project Observation Report

Observer Name: [REDACTED]
Phone: [REDACTED]
Email: [REDACTED]
Date of Report 2022-01-05

(B)



(C)

